Cannot boot miniroot

Published 06/03/2002

Symptom(s):

```
Tezro can not boot miniroot
Can not boot miniroot in Tezro
System will not boot to miniroot or inst from CDROM
Can't boot miniroot
Error: "TLB refill exception error on node 0"
Read TLB miss exception, bad address: 0x1c
Error from Selecting "Install Software" from 5-option menu produced:
Error: "*** TLB Refill Exception on node 0"
Error: " *** EPC: 0xa80000000129c854 (0xa80000000129c854)"
```

Fact(s):

```
IRIX 6.5.X
Silicon Graphics Fuel
Silicon Graphics Tezro
SGI Onyx 3400
Odyssey (VPRO) Graphics
VPro graphics
setenv console g
```

SGI Solution:

```
Install USB keyboard and mouse and use the graphics console, or
set the PROM/miniroot console to d
setenv console = d
```

Cause(s):

```
PROM variable 'console' was set to 'g' and the keyboard and mouse were not installed.
```

Answers others found helpful

- How to repair corrupted root file system
- How to shut off the SGI Apache webserver
- USB support under IRIX
- SYSLOG Error: 'ALERT: I/O error in filesystem meta-data dev <devid> block <blockid> ("xfs_trans_read_buf")'
- How to boot miniroot

Additional Details

Creation Date	01/29/2002 07:23 AM
Last modification	01/15/2016 04:29 PM
Published Date	06/03/2002
Products	• Servers and Clusters • SGI Origin/Onyx • Origin/Onyx Server • Software • Legacy Software • Operating Systems • IRIX • Workstations • SGI Tezro • SGI VPro • O2 • Octane
Categories	• Knowledgebase • Technical Solution